



GREENFIELD FIRE TERRITORY

Fire Prevention Division

17 W. South ST, Greenfield IN / (317) 325-1505 / Brian D. Lott, Fire Marshal

Occupant Name:	Greenfield Police Department	Inspection Date:	12/10/2018
Address:	116 South State Street	InspectionType:	Annual
Suite:		Inspected By:	Brian Lott

Insp. Result	Location	Code Set	Code
--------------	----------	----------	------

Fail	Floor -1	IN Fire Code 2014 CHAPTER 10 - MEANS OF EGRESS	1011.3 - Exit signs illuminated.
-------------	----------	---	----------------------------------

Comment: Illumination.
Exit signs shall be internally or externally illuminated. Exception: Tactile signs required by Section 1011.4 need not be provided with illumination.

north exit door

Fail	Floor -1	IN Fire Code 2014 CHAPTER 10 - MEANS OF EGRESS	1006.3 - Emergency egress illumination.
-------------	----------	---	---

Comment: Emergency power for illumination.
The power supply for means of egress illumination shall normally be provided by the premises' electrical supply. In the event of power supply failure, an emergency electrical system shall automatically illuminate all of the following areas:

1. Aisles and unenclosed egress stairways in rooms and spaces that require two or more means of egress.
2. Corridors, interior exit stairways and ramps and exit passageways in buildings required to have two or more exits.
3. Exterior egress components at other than their levels of exit discharge until exit discharge is accomplished for buildings required to have two or more exits.
4. Interior exit discharge elements, as permitted in Section 1027.1, in buildings required to have two or more exits.
5. Exterior landings as required by Section 1008.1.6 for exit discharge doorways in buildings required to have two or more exits.

The emergency power system shall provide power for a duration of not less than 90 minutes and shall consist of storage batteries, unit equipment or an on-site generator. The installation of the emergency power system shall be in accordance with Section 604.

north exit to stairs, south exit to stairs

Fail	Floor -1	IN Fire Code 2014 CHAPTER 9 - FIRE PROTECTION SYSTEMS	903.3.3 - Sprinkler obstructions.
-------------	----------	--	-----------------------------------

Comment: Obstructed locations.
Automatic sprinklers shall be installed with due regard to obstructions that will delay activation or obstruct the water distribution pattern. Automatic sprinklers shall be installed in or under covered kiosks, displays, booths, concession stands or equipment that exceeds 4 feet (1219 mm) in width. Not less than a 3- foot (914 mm) clearance shall be maintained between automatic sprinklers and the top of piles of combustible fibers. Exception: Kitchen equipment under exhaust hoods protected with a fire-extinguishing system in accordance with Section 904.

All drop ceilings needs sprinkler heads dropped below them. Also in the sprinkler room I could not find a sprinkler head.

Fail	Floor -1	IN Fire Code 2014 CHAPTER 5 - FIRE SERVICE FEATURES	506.1 - Knox Box.
-------------	----------	--	-------------------

Comment: When Required.

Whenever the servicing fire department has instituted a key box emergency access system, a key box compatible with that system shall be installed in an accessible location if:

- (1) The building is protected with an automatic sprinkler system equipped with a local or transmitted water-flow alarm, or
- (2) The building is provided with any fire alarm system equipped with an outside audible/visual signaling device, or
- (3) The building is provided with any fire alarm system where the alarm is transmitted to an off-site location, or to the fire alarm center for the servicing fire department.

Fail Floor -1 IN Fire Code 2014
CHAPTER 9 - FIRE PROTECTION SYSTEMS 901.6 - Fire detection, alarm, and extinguishing systems maintained in an operative condition at all times.

Comment: Inspection, testing and maintenance.
Fire detection, alarm, and extinguishing systems, mechanical smoke exhaust systems, and smoke and heat vents shall be maintained in an operative condition at all times, and shall be replaced or repaired where defective. Nonrequired fire protection systems and equipment shall be inspected, tested and maintained or removed

HVAC trouble is shown on the alarm panel that needs addressed.
Alarm needs to be monitored.

Fail Floor -1 IN Fire Code 2014
CHAPTER 9 - FIRE PROTECTION SYSTEMS 901.4 - Alteration and maintenance of fire protection systems.

Fail Floor -1 IN Fire Code 2014
CHAPTER 9 - FIRE PROTECTION SYSTEMS 904.3.5 - Sprinkler system monitored by fire alarm.

Comment: Monitoring.
Where a building fire alarm system is installed, automatic fire-extinguishing systems shall be monitored by the building fire alarm system in accordance with NFPA 72.

Fail Floor -1 IN Fire Code 2014
CHAPTER 9 - FIRE PROTECTION SYSTEMS 903.5 - Automatic sprinkler system tested and maintained.

Comment: Testing and maintenance.
Sprinkler systems shall be tested and maintained in accordance with Section 901.

There are 5 different issues that need addressed from the sprinkler inspection report.

Fail Floor 1 IN Fire Code 2014
CHAPTER 5 - FIRE SERVICE FEATURES 506.1 - Knox Box.

Comment: When Required.

Whenever the servicing fire department has instituted a key box emergency access system, a key box compatible with that system shall be installed in an accessible location if:

- (1) The building is protected with an automatic sprinkler system equipped with a local or transmitted water-flow alarm, or
- (2) The building is provided with any fire alarm system equipped with an outside audible/visual signaling device, or
- (3) The building is provided with any fire alarm system where the alarm is transmitted to an off-site location, or to the fire alarm center for the servicing fire department.

Fail Floor 1 IN Fire Code 2014
CHAPTER 9 - FIRE PROTECTION SYSTEMS 906.9.1 - Mounting height of fire extinguishers at or below 5 ft.

Comment: Extinguishers weighing 40 pounds or less.
Portable fire extinguishers having a gross weight not exceeding 40 pounds (18 kg) shall be installed so that their tops are not more than 5 feet (1524 mm) above the floor.

Front office extinguisher needs mounted

Fail Floor 1 IN Fire Code 2014
CHAPTER 10 - MEANS OF EGRESS 1011.3 - Exit signs illuminated.

