





Water Utility

2018 Monthly Report October



Month	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sept	Oct	Nov	Dec	Total
Total Finished Water MG 2018	74.73	67.37	68.80	68.43	86.56	83.16	86.28	84.71	78.16	73.92			772.11
Total Finished Water MG 2017	67.42	63.58	71.17	67.79	79.83	77.78	80.79	81.31	74.05	71.00			734.72
Variation 2018 vs 2017	7.31	3.79	2.37	0.64	6.73	5.38	5.49	3.40	4.11	2.92			14.11
2018% of Production Capacity	37%	35%	39%	37%	44%	43%	44%	39%	37%	35%			39%
Highest Month production day	2.83	2.61	2.41	2.80	3.24	3.15	3.19	3.24	2.90	2.90			2.89
Total completed work orders	172	150	114	205	357	481	405	194	234	245			
2018 Precipitation totals	3.13	5.05	5.59	4.43	3.02	7.17	7.23	7.11	8.71	2.06			
2017 Precipitation totals	4.90	0.44	4.26	3.64	9.56	3.77	10.09	1.57	0.58	3.41			

Normal production
Single main break
Multiple Main breaks
Fire
Flushing





Water Utility

2018 Monthly Report October



Work Type	Total	Complete	New Request	Work In Progress	Work Type	Total	Complete	New Request	Work In Progress
Building Maintenance	3	0	3	0					
Check for Leak	3	2	1	0					
Construct Meter Lid	1	1	0	0					
Construction Inspection	1	1	0	0					
D.S. Sampling	19	19	0	0					
Discolored Water	15	5	1	9					
Grounds Maintenance - Source	2	2	0	0					
Hydrant Flushing	6	6	0	0					
Hydrant Painting	16	15	0	1					
Hydrant Repair	2	1	1	0					
Hydrant Service	2	2	0	0					
Install New Service	9	5	3	1	total	292	245	35	12
Leak Repair - Service	2	2	0	0					
Locate	7	1	6	0	WORK ORDERS TO NOTE				
Map Correction Request	6	0	6	0	WILSON ST	RETIRED 2 OLD SERVICE LINES, AND REMOVED A BROKEN VALVE			
Meter Pit Inspection	14	14	0	0	EAST WATER TOWER	TAKEN OFFLINE, STANDPIPE REPAIRED, PLACED BACK IN SERVICE			
Misc - Plant	8	7	1	0	OSAGE ST	REPLACED TWO OLDER SERVICES WITH NEW SETTINGS			
Misc - Source	2	1	0	1	N STATE ST	REPAIRED VALVE BOX TOP			
Seasonal Turn Off	1	1	0	0	GASLITE	REPAIRED LEAKING VALVE AT MAIN			
Security	1	1	0	0	BROADWAY	RETIRED OLD SERVICE LINES AND INSTALLED TWO NEW SERVICE LINES			
Turn Off	5	5	0	0	Well 1-3 work	Work is progressing on the initial survey and geotech work			
Turn On	6	5	1	0					
Vac Out Valve Box	6	3	3	0					
Valve Exercise	139	139	0	0					
Valve Inspection	3	0	3	0					
Valve Maintenance - Plant	1	0	1	0					
Valve Repair	6	1	5	0					
Vehicle Inspection	4	4	0	0					
Vehicle Maintenance	2	2	0	0					