


Wastewater Utility 2018 Monthly Report



November 2018



| Month | January | February | March | April | May | June | July | August | September | October | November | December | Total |
|----------------------------------|---------|----------|--------|--------|--------|-------|--------|--------|-----------|---------|----------|----------|---------|
| Total MG Treated Effluent 2018 | 91.20 | 125.71 | 114.45 | 126.25 | 75.78 | 85.60 | 98.27 | 115.29 | 132.71 | 79.28 | 120.06 | 0.00 | 1164.6 |
| Total MG Treated Effluent 2017 | 136.22 | 65.49 | 94.38 | 91.49 | 165.21 | 94.02 | 129.60 | 70.19 | 57.56 | 63.78 | 80.53 | 64.54 | 1113.01 |
| Total Monthly Precipitation 2018 | 2.32 | 5.42 | 4.27 | 4.54 | 2.80 | 6.69 | 8.14 | 7.48 | 11.10 | 2.31 | 5.14 | 0.00 | 60.21 |

| | | | | | | | | | | | | | |
|-------------------------------|-----|------|-----|------|-----|-----|-----|-----|------|-----|------|--|--|
| 2018 Monthly Percent Capacity | 73% | 112% | 92% | 105% | 61% | 71% | 79% | 93% | 111% | 64% | 100% | | |
| Actual Design Flow 4.0 MGD | | | | | | | | | | | | | |

Sewer Crew Activities

Catch Basins Repaired

Major Storm Sewer Project

New Laterals Inspected

Major Projects Completed

Other Projects Completed

Emergency Repairs

Plant Crew Activities

Sludge Pressed / Gallons

Motors Repaired/Replaced

System Repairs

872,000

Replaced #2 Back Wash Valve Operating Motor & Shaft

Plant Crews Worked On Flipping The Plastic Chain & Scraper System As We Continue To Waite For Repair Parts

Thanks To The Street Dept> For Allowing Us To Use Their New Very Clean Payloader

Ordered A New 8" Check Valve For The Imhoff Tank, It Had Been Leaking For Quite Some Time

Near W. Main & School St.

Due To The Lack Of Neighborhood Support

Only One Section Of Pipe Was Installed

8 Homes

Both Lift Station Pump Discharge Elbows Had

To Be Replaced, Unfortunately Twice

We Were Coerced To Help INDOT Excavate A

Bad Spot On South State Street - Not Guilty

331 North East St. & 1008 East 5th St.