





Water Utility 2018 Monthly Report DECEMBER



Month	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sept	Oct	Nov	Dec	Total	
Total Finished Water MG 2018	74.73	67.37	68.80	68.43	86.56	83.16	86.28	84.71	78.16	73.92	67.40	68.99	908.51	Normal production
Total Finished Water MG 2017	67.37	61.18	78.54	75.27	79.83	84.78	80.79	81.31	74.05	71.00	63.76	66.36	884.24	Single main break
Variation 2018 vs 2017	7.36	6.19	9.74	6.84	6.73	1.62	5.49	3.40	4.11	2.92	3.64	2.63	24.27	Mutiple Main breaks
2018% of Production Capacity	37%	33%	43%	41%	44%	46%	44%	39%	37%	35%	31%	32%	39%	Fire
Highest Month production day	2.83	2.61	2.41	2.80	3.24	3.15	3.19	3.24	3.03	2.90	2.51	2.53	2.89	Flushing
Total completed work orders	172	150	114	205	357	481	405	194	234	245	170	146	2873	
2018 Preciptation totals	3.13	5.05	5.59	4.43	3.02	7.17	7.23	7.11	8.71	2.06	5.10	2.96	61.56	
2017 Preciptation totals	4.90	0.44	4.26	3.64	9.56	3.77	10.09	1.57	0.58	3.41	4.90	1.65	48.77	



2018 Monthly Report for December					2018 Annual Report									
Work Type	Total	Complete	New	Work In	Work Type	Total	Complete	New	Work In	Work Type	Total	Complete	New	Work In
			Request	Progress				Request	Progress				Request	Progress
Assist Other Utilities	1	1	0	0	Assist Other Utilities	7	6	0	1	Misc - Plant	61	59	1	1
Building Maintenance	2	0	2	0	Building Maintenance	32	12	19	1	Misc - SCADA	8	5	2	1
Check for Leak	5	5	0	0	Building Material Conditi	3	2	1	0	Misc - Source	37	27	5	5
D.S. Sampling	28	28	0	0	Check for Leak	90	88	1	1	Misc - Tower	1	1	0	0
Discolored Water	5	5	0	0	Communication/Power	6	1	1	4	Plant Activity	4	3	0	1
Enclosure Material Condition	1	0	0	1	Concrete Repair	4	2	2	0	Pump Maintenance	4	3	0	1
Hydrant Flushing	16	16	0	0	Construct Meter Lid	10	9	1	0	Raise/Lower Setting	15	13	1	1
Hydrant Inspection	1	1	0	0	D.S. Sampling	294	293	1	0	Replace ERT/Antenna	2	2	0	0
Hydrant Service	1	1	0	0	Dirt Work	40	40	0	0	Replace Hydrant	1	1	0	0
Install New Service	3	3	0	0	Discolored Water	73	68	0	5	Replace Meter	2	2	0	0
Leak Repair - Service	1	1	0	0	Enclosure Material Conditio	4	2	0	2	Replace/Repair Meter	12	9	3	0
Locate	6	6	0	0	Grounds Maintenance - Pl	8	6	1	1	Retire Old Service	10	6	4	0
Low Pressure/Frozen Service	1	0	1	0	Grounds Maintenance - So	5	5	0	0	Seasonal Turn Off	18	17	1	0
Main Break	2	2	0	0	Grounds Maintenance - To	5	5	0	0	Seasonal Turn On	14	14	0	0
Meter Pit Inspection	15	15	0	0	Hydrant Flushing	125	125	0	0	Security	1	1	0	0
Misc - Plant	5	4	0	1	Hydrant Inspection	11	10	1	0	Sensor	1	1	0	0
Misc - Source	9	9	0	0	Hydrant Painting	86	85	0	1	Source Activity	1	1	0	0
Retire Old Service	3	3	0	0	Hydrant Repair	22	17	4	1	Tower Activity	1	1	0	0
Seasonal Turn Off	7	5	2	0	Hydrant Service	38	38	0	0	Turn Off	126	126	0	0
Turn Off	11	11	0	0	Install New Meter	5	4	0	1	Turn On	102	100	1	1
Turn On	7	7	0	0	Install New Service	41	37	4	0	Vac Out Pit	6	5	1	0
Vac Out Pit	1	1	0	0	Leak Repair - Service	21	20	0	1	Vac Out Valve Box	61	53	8	0
Valve Exercise	5	5	0	0	Locate	48	26	22	0	Valve Exercise	1193	1182	9	2
Valve Repair	2	2	0	0	Low Pressure/Frozen Servi	65	64	1	0	Valve Inspection	15	3	12	0
Vehicle Inspection	11	11	0	0	Main Break	17	17	0	0	Valve Maintenance - Plant	2	1	1	0
Vehicle Maintenance	4	4	0	0	Main Retirement	1	1	0	0	Valve Repair	116	46	68	2
					Map Correction Request	69	26	41	2	Vehicle Inspection	107	106	1	0
					Material Condition	1	1	0	0	Vehicle Maintenance	32	31	0	1
					Meter Pit Inspection	177	176	1	0	Well Inspection	4	2	1	1
					Misc - Activity	8	7	0	1	Well P.M.	12	5	0	7
Mthly Work Order Total	153	146	5	2	Work Order Sub-Total	1184	1085	80	19	Total Work orders 2018	1862	1734	111	17